





Cleaning and maintenance

Suspended and self-supporting ceilings

Valid for:

Contur 600	Plaza 600
Linear 600	Danoline Tiles 600
Markant 600	Corridor 300
Belgravia 600	Corridor F30
Markant 500	Corridor Swing 600

Materials:

Tiles and Panels:	Factory painted perforated and unperforated ceiling tiles and panels are painted with water based acrylic paint. Standard White no. 7380-3350 (as NCS 0700) gloss 5. Danoline Tiles 600 and Corridor F30 are factory laminated with a white, metallic or medley face.
Suspension system:	Galvanised metal profiles, the exposed parts are factory painted as CMC No. 001 Global White (NCS 0902-G48Y), wall angle for Corridor F30 as RAL 9010.

Maintenance:

Dust:	Vacuum cleaning with a soft brush nozzle.
Dirt:	Painted surfaces should be wiped off with a damp cloth, using a mild detergent. Laminated surfaces can be washed.
Stains and damages:	Painted surfaces should be wiped off and if necessary repainted using a paint roller or a brush, but roller is recommended. Spray painting is not recommended on perforated products, as the spray paint could be applied to the acoustic felt backing altering the acoustic properties. Slight damages and scratches on the surface can be repaired using filler and finishing with sandpaper. The painted ceiling products can be repainted using Danogips repair paint colour no. 7417-3350 (as NCS 0700). Laminated products being damaged with scratches shall be replaced.

References:

Danoline product literature.



Ceiling linings, acoustic and plain

Valid for:

Danopanel

Contrapanel

Combipanel

Kinopanel

Designpanels 900 and 1200

Curvex (arches)

Tectopanel

Mitex (folded panels)

Materials:

Panels:

Factory painted perforated and unperforated panels are painted with water based acrylic paint. Standard White no. 7380-3350 (as NCS 0700) gloss 5. Contrapanel is factory laminated with a white face.

Maintenance:

Dust:

Vacuum cleaning with a soft brush nozzle.

Dirt:

Painted surfaces should be wiped off with a damp cloth, using a mild detergent.

Stains and damages:

Painted surfaces should be wiped off and if necessary repainted using a paint roller or a brush, but roller is recommended. Spray painting is not recommended on perforated products, as the spray paint could be applied to the acoustic felt backing altering the acoustic properties.

Slight damages and scratches on the surface can be repaired using filler and finishing with sandpaper.

The painted ceiling products can be repainted using Danogips repair paint colour no. 7417-3350 (as NCS 0700).

References:

Danoline product literature.